

Spare parts

The spare parts can be used for all our 3D Tester models.



Easy screwing in and unscrewing of the probe tip thanks to the practical borehole.

Two hexagon keys size 2 are supplied with each 3D Tester Universal and DREHplus.

Article No.	Description	Length	Tester
00163CN03	Probe tip ceramic	approx. 27 mm	Ø3
00163C006	Probe tip long ceramic	approx. 62 mm	Ø6
00163D099	Seal for 3D Tester	-	-
001D32450	Spare battery CR2450	-	-



Important Note:

When changing the probe tip, make sure not to damage the seal (see picture 1.), and check the run-out each time after changing the probe tip (see picture 2.). You will find a detailed description in the operating instructions.



Videos for training



3D Tester:
Scope of delivery



3D Tester:
Run-out



3D Tester:
Probing



Repair service



Crashed?

All our 3D-Testers can be repaired.

Our worldwide resellers support you for any repair or service question.

